


Panther Project Pictures

First Hill Climb - Before



After



Example of plugged up culverts - Before




Photo on first hill climb, dug 3' down and back to find culvert



Sloughed in area where trail was under 6' wide
Before photo from 2020, trail condition worse in 2025



Trail width restored, culverts cleaned, and
erosion rocks placed around culverts



General Trail Cleanup

Trail was 2 different heights, leveled it and added a flat spot midway for wagons to take a break



General cleanup

